

PRIMARY CORNER DESCRIPTION SW cor. Sec. 31 (SW Tsp. Cor.)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1499)

-----  
Intersect 5th standard parallel 3.20 chs. W. of standard cor. and set post cor. of T22S., Rs. 7 and 8 W., from which  
A B.Oak 18" dia., bears N.17°E., 193 lks. dist.  
An Alder 8" dia., bears N.75½°W., 887 lks. dist.

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13670)

-----  
Point for the closing cor. of Tps. 22 S., Rs. 7 and 8 W., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

CC  
T 22 S  
R 8 W R 7 W  
S 36 S 31  
S 1  
T 23 S R 8 W  
1964

from which

A Fir 18" dia., bears N.47½°E., 170 lks. dist. mkd. T22S R7W S31 CC BT.

A Fir 11" dia., bears N.76½°W., 152 lks. dist. mkd. T22S R8W S36 CC BT.

Deposit broken brown glass at base of iron post.

FD OK By D.Bentz, M 117-6, 5/93

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 8/5/2002 - C.S. File 66/34-30

-----  
Found - 1964 BLM brass cap iron pipe, flush with ground.  
11" now 26" dia., D.Fir with a fully healed blaze bears N.76½°W., 100.3 ft. (1964)  
18" now rotted 1½ high D.Fir stump no scribing found rotted blaze, bears N.47½°E., 112.2 ft. (1964)  
New - 19" dia., D.Fir double blazed & scribed "CC T22S R7W S31 CS BT" bears N.59½°E., 27.4 ft. ft.  
17" dia., D.Fir double blazed & scribed "T22S R8W CC S36 CS BT" bears N.8½°W., 22.8 ft.  
9" dia., Maple double blazed & scribed "CC T22S R7W S31 CS BT" bears N.27½°E., 45.0 ft.  
Compass decl. 17¼°E.