

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by John G. Collins, US Cadastral Engineer & Otto L. Draper, U.S. Transitman, under Special Instructions dated March 12, 1921, surveyed July 1928/Aug. 1930 - (DCSO records Vol. 22 Page(s) 9294)

A cedar, 5" dia., for the 1/4 sec. cor. of secs. 10 & 11; I mark
 1/4 S 10 on W
 and S 11 on E sides
from which
 A cedar, 10" dia., bears N.59°E., 19 lks., mkd: 1/4 S11 BT.
 A hemlock, 8" dia., bears N.46°W., 18 lks., mkd: 1/4 S10 BT.

Dennis Gaylord, USFS & DCSO - Bill West - Oct. 26, 1978 - C.S. File 59/30 moved to C.S. File 62/50-9

Referenced notes only
Found - 7" cedar corner tree, is still standing but nearly dead. Unhealed blazes show scribing of "1/4" on the west and "S11" on the east.
 11" hemlock snag with a healed blaze bears N.49°30'W., 13.1 ft. (Rec. N.46°W., 11.88 ft.)
 A 16" cedar snag bears N.62°30'E., 11.9 ft. (Rec. N.59°E., 12.54') Previously opened blaze has scribing "1/4 S11/BT"
This corner falls in a proposed landing & will therefore be destroyed during construction.
New - A 5/8"x36" I. rod with a 1 1/2" alum. cap attached bears N.80°30'E., 70.7 ft.
 17" cedar bears N.18°E., 56.1 ft. scribed "1/4 S11 CS BT" on a double blaze.
 A 5/8"x36" I. rod with a 1 1/2" alum. cap attached bears N.47°30'E., 64.9 ft.
Placed county BT signs on all 3 BTs and on corner tree.

Douglas Co. Surveyors Office - Stephen J. Flause - Randall W. Smith - March 30, 1988 - C.S. File 62/50-9

Found - Rotted remains of cedar stump protruding approx. 6" above ground from dead but sound cedar roots. Growth pattern supported a small tree.
Area has been logged and burned. No evidence is found of the scribed trunk of the corner tree.
Orig. BT, a cedar 10" dia. now a 16" DBH fallen and burned cedar with partial illegible scribing visible on a previously opened and now burned blaze. The well defined root-hole of this tree bears N.59°E., 12.5 ft. (As per record) Cont.

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

No evidence is found of the original northwest BT.
All new accessories from 1978 Renewal found:

A 5/8"x36" I.Rod with a 1½' alum. cap stamped "S80-30W 70.7' R.M." with an arrow pointing toward the corner position is firmly set and protrudes approx. 7" above ground & bears N.74°E., 70.7' (Rec. N.80°30'E., 70.7 ft.)

A 17" cedar now a 19" DBN I.Cedar with the scribing "¼ S11 CS BT" visible in a partially healed double blaze bears N.14°E., 56.1 ft. (Rec. N.18°E., 56.1 ft.)

A 5/8"x36" I.Rod with a 1½" alum, cap stamped "S47-30W 64.9 ft. R.M." with an arrow pointing toward the corner position is firmly set and protrudes approx. 5" above ground and bears N.41½°E., 66.6 ft. (Rec. N.47°30'E., 64.9 ft.)

Set - The corner position is perpetuated by establishing a brass cap monument within the apparent remains of the corner tree. This position agrees well with the well defined remaining evidence of the original northeast BT. Two out of three distances to the references from 1978 Renewal agree well with record and the distance to the NNE reference would indicate a possible error in slope measurement. Bearings from corner tree remains to the references from 1978 Ren. indicate a possible problem with compass declination. Monument set is 20" dia. brass cap marked "Douglas County Surveyors T25S ¼ S10|S11 R2E 1988" on a 1" I.D. 32" long iron pipe protruding 10" above ground.

New BT - A 17" dia. 2 foot tall cedar stump with a boat spike driven into stump through a bearing tree tag. Boat spike is stamped "BO 1" and bears S.81°W., 24.5 ft. dist. from BC monument.

Monument on a northwest slope at top of clearcut and just off of log landing at turn to east in USFS Road #3850.