

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T32-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 19 Page(s) 8246)

Set a basalt stone 14x10x10 ins., 10" in the ground, cor. to secs. 13, 18, 19 and 24, 300 ft. below top of Umpqua divide, mkd. with 3 notches on N. and S. edges, from which
A Yew 6" dia., bears N.50°E., 15 lks. dist. mkd. T32S R1W S18 BT.
A Fir 22" dia., bears S.23°E., 15 lks. dist. mkd. T32S R1W S19 BT.
A Fir 10" dia., bears S.18°W., 44 lks. dist. mkd. T32S R2W S24 BT.
A Yew 8" dia., bears N.70°W., 8 lks. dist. mkd. T32S R2W S13 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darbey & Wm. Stoffel, crew - March 1963 - C.S. File 53/15

Found - Orig. 6" now 8" Yewwood N.50°E., 9.9 ft., shows good scribing.

No other orig. BTs. Find stone as recorded.

Set Brass cap at cor. mkd: County Surveyors Office

T 32 S
R2W S 13 | S 18 R1W
S 24 | S 19
1963

New BTs- 18" Yewwood bears S.40°E., 18.3 ft. scribed S19 T32S R1W CS BT.

19" W.Fir bears N.55°W., 82.7 ft. scribed S13 T32 R2W CS BT.

No trees near to SW.

Glenn S. Baughman - For: U.S. Forest Service - Dec. 1976 - M 56-69

Found - 1963 DCSO brass cap.
8" Yew bears N.50°E., 9.9 ft.
18" Yew bears S.40°E., 18.3 ft.
20" W.Fir bears N.55°W., 82.7 ft.

New BT - 6" Fir bears S.75°W., 22.6 ft. "T32S R2W S24 BT"

Survey by Don Bentz - For: U.S. Forest Service - July 19, 1993 C.S. File 63/153

Found - 8" Yew with visible scribing, bears N.50°E., 9.9 ft.
18" Yew with visible scribing bears S.40°E., 18.3 ft
(Cont. Next Page)

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 100400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T32-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

19" Yew (S.46°E.) (18.3 ft) scribe on part. healed double blaze
23" W.Fir (N.56°W.) (82.7 ft) healed double blaze
17" Fir (S.70°W.) (22.6 ft) healed double blaze
() = Record per 2002 BLM record

No new accessories added

New nails in BT tags and painted faces & 6" band at head height

Brush cleared around monument and to BTs.

"LAND LINE" flagging tied on monument & guard posts
Corner falls on slight north slope at corner of recent private clear cut, take highway to intersection of closed private logging road on south'ly side of clear cut unit, follow road on foot west-south west to end, then south west to timber corner.

Property line maintained east .5 miles

Douglas Co. Surveyors Office - Stephen J. Flauser - Mike Koch - July 11, 2014 - C.S. File 67/41-26

Condition report only

Found - As described in 2002 but:

The 1963 DCSO brass cap/iron pipe monument is found loose on ground surface near 2002 BLM monument. DCSO monument is not practicable to reset, we remove from area to avoid future confusion.

Accessories found as described in 2002

Note - Monument is just inside edge old fir forest which was recently clear-cut in the NE quadrant
Compass decl. 15½°E.