

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1510)

Set ¼ sec. post, from which
A Fir 48" dia., bears S.80°E., 44 lks. dist.
A Fir 50" dia., bears S.12°W., 50 lks. dist.

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1523)

Set ¼ sec. post, from which
A W.Oak 3" dia., bears S.80°E., 20 lks. dist.
A W.Oak 5" dia., bears S.30°W., 37 lks. dist.

A Boyer - August 1913 - Vol. 2 Page 254 and Field book 34 Page 4

Set Cedar post marked C.S.
Fir 12" S.44½°W., 27 lks.
Fir 14" S.49½°E., 32 lks.

Wilford N. Haines - For: Yoncalla Lumber Co. - March 1961 - M 22-1

Found - Two Fir BTs scribe by C.S. in 1931 (1913?)
SE BT, now a stump.
Set 1" x 1" x 36" T. Iron.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - March 1962 - C.S. File 52/14-117

Found - Haines T Iron at corner.
Rotted remnants of Fir stumps in stump holes. This is all that remains of orig. BTs.
Fir stump 18", S.49½°E., 21.1 ft. Portion of scribe mark visible on old face near top of stump.
Fir tree 18", S.44½°W., 17.8 ft., shows good scar. This tree still alive and in good condition. (This tree and stump mkd. by Eppstein in 1931) (1913?)

Did not set Brass cap.
New BT - 3" D.Fir S.86°E., 41.0 ft. mkd. ¼ S16 CS BT.
A fence cornr bears East approx. 50 ft. fences N. S. & W.
This is Gordon and Gardiner ¼ cor. estab. in 1855.

Fd. OK, May 4, 1989, L. Roberts, C.S. File 63/91 & M 108-22

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 3/11/1998 - C.S. File 66/2-5

Found - T-iron, protrudes 6" above ground. 1961 Haines
3" now 13" dia. D.Fir with a healed blaze, bears
S.86°E., 41.0 ft. (Agrees with rec.) 1962 DCSO
(We rescribe "¼ S16 CS BT" on a single blaze)
14" now nearly rotted to ground remains of a D.Fir
stump found near record bearing "S.49½°E., 21.1
ft." no blazes or scribing visible. 1913 Boyer
12" now 24" dia. 2 ft. high D.Fir stump, no blazes
visible, bears S.49°W., 17.8 ft. (Rec.
S.44½°W., 17.8 ft.) Stump is solid. 1913 Boyer
New BTs- 15" dia. D.Fir, double blazed and scribed "¼ S17
CS BT" bears N.84°W., 35.3 ft.
13" dia. pistol butt Maple, with fence wire on
North and South side of trunk, single blazed 5
ft. above ground "¼ 16 CS BT" center of root
crown, bears S.89°E., 21.4 ft.
Note - Aluminum witness post is 1 ft. East of T-iron.
Fence corner with fence running North and West
approx. 50 ft. East of corner.
1962 DCSO renewal notes this corner is the 1855
corner.
See sketch in file.