

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Standard Cor. for Secs. 34 & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 7 Page(s) 2700)

Set a Yew post 5 ft. long, 5" dia., 20" in the ground for the corner to secs. 2, 3, 34 and 35, from which
A Fir 36" dia., bears N.15°E., 37 lks. dist.
A Fir 20" dia., bears S.58°E., 17 lks. dist.
A Fir 20" dia., bears S.61°W., 24 lks. dist.
A Fir 30" dia., bears N.3°W., 42 lks. dist.

Fd. and tied in GLO survey by Levi C. Walker, Deputy Surveyor, under Contract #763, dated June 20, 1905 - (DCSO records Vol. 7 Page(s) 2722)

Donald L. Peel - For: Weyerhaeuser Co. - March 1967 - C.S. File 55/30-1

Found - GLO survey record, post gone.
36" Fir N.15°E., 37 lks.; now 30" Fir stump, nothing visible, probably bark scribing.
20" Fir S.58°E., 17 lks., markings destroyed in 1896,; now 26" Fir snag, face visible.
20" Fir S.61°W., 24 lks.; markings visible in 1896, now 32" Fir, face visible.
30" Fir N.3°W., 42 lks.; now Fir snag, face visible, chopped open, but rotted from inside, no scribing left.
Set 3/4" x 4 ft. pipe, 3½ ft. into the ground for corner and re-referenced with "W" nails and Weyerhaeuser tags:
10" hemlock N.10°E., 19.8 ft.
24" Hemlock N.80°W., 23.4 ft.

Fd. OK, July 31, 1973 by DCSO - C.S. File 56/35

Douglas Co. Surveyors Office - Clell Goodwin and Lenora Ladig, crew - June 17, 1975 - C.S. File 57/30

Found 3/4" pipe set by Weyerhaeuser and remains of all original BTs.
Set 1½" Iron pipe flanged on bottom, projecting 1 ft. out of ground, from which a
10" Hemlock bears N.10°E., 212 ft. scribed "S35 X" in single blaze.
24" Hemlock bears N.80°W., 24.4 ft. scribed "X S34".