

PRIMARY CORNER DESCRIPTION Cor. Sec. 10 only (Southeast)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO records Vol. 7 Page(s) 2713-14)

Set a Fir post, 5 ft. long, 5 ins. dia., 20" in the ground for the corner to secs. 10, 11, 14 & 15, from which
A Fir, 10" dia., bears N.23°E., 95 lks.
A Fir, 50" dia., bears S.45°E., 72 lks.
A Fir, 20" dia., bears S.75°W., 54 lks.
A Fir, 8" dia., bears N.15°W., 131 lks.

GLO resurvey and retracement by Levi C. Walker under contract #763, dated Aug. 23, 1905 - (DCSO records Vol. 7 Page(s) 2733)

Set a Fir post, 3 ft long, 4" sq., 24" in the ground, for the SE Cor. of sec. 10 mkd: T23S S11 on NE, R10W S11 on SE, S11 on SW & S10 on NW face, with 4 notches on S & 2 notches on E edge; from which
An Alder, 14" dia., bears N.15°E., 11 lks., mkd: T23S R10W S11 BT.
A Fir, 18" dia., bears N.55°W., 22 lks., mkd: T23S R10W S10 BT.

Arnold G. Gibson, Oregon St. Board of Forestry - Dec. 8, 1972 - M 49-20

Sec. Cor. reestablished
Set - OSBF iron pipe with 3" bronze cap, 12" in ground.
20" Fir, N.16°W., 183.4 ft. with yellow metal location poster.
16" Fir N.50°W., 149.1 ft. (RS359)
4"x4"x72" white painted cedar post North 2.0 ft.

Arnold G. Gibson, St. of Oregon, Dept. of Forestry - Witnessed by James M. McIntosh - June 14, 1976 - C.S. File 58/31

No evidence of orig. corner found.
Restoration by A. Gibson, 1972
Found - 1½"x36" GIP, missing in recently logged area, from which a:
20" Fir, N.16°W., 183.4 ft., now 22" stump in place, scribes T23S R10W S10 BT visible.
16" Fir N.50°W., 149.1 ft., now 18" stump in place, scribes T23S R10W S10 BT RS 359 visible.
4"x4"x72" WPCP bears North 2.0 ft., found, knocked out of place by recent logging.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Sec. 10 only (Southeast)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Set - 1½"x36" galv. iron pipe with 3" bronze cap mkd:
OREGON STATE BOARD OF FORESTRY T23S R10W S10 S11
1976 RS359, 34" in ground.

Reset - 4"x4"x72" white painted Cedar post N.20°W., 1.6 ft.
from corner pipe.
Oregon State Forestry Dept. metal location poster on
4"x4"x72" WPCP

Oregon Dept. of Forestry, James McIntosh - Witness: Ralph C.
Hall - Sept. 26, 2000 - C.S. File 65/33-2

Found - No orig. evidence found.
From 1972 ren. -
Oregon State Board of Forestry 1½"x36" galvanized
iron pipe with 3" bronze cap (missing) from
which a:
20" Fir N.16°W., 183.4 ft; now 21"x3' high rotted
stump in place, axe work visible on bark.
16" Fir N.50°W., 149.1 ft. now 10"x3' high rotted
stump in place, axe work visible on bark.

From 1976 ren. -
Oregon State Board of Forestry 1½"x36" galvanized
iron pipe with 3" bronze cap, 1976, in place
Reset (in 1976) 4"x4"x72" white painted cedar
post N.20°W., 1.6 ft. with yellow metal
location poster; now rotted & fallen over.

Rewitnessed from the above pipe & cap -
8" Fir N.71°W., 27.1 ft. to alum. nail in BT face
scribed T23S R10W S10 BT. BT tag.
Carsite witness post N.17°W., 3.9 ft. to base.
Carsite witness post N.89°W., 2.6 ft. to base.

Note - Magnetic variation set at 20°E.