

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 540100

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 35 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 7 Page(s) 2700)

Marked a Fir 5" dia., for the ¼ sec. cor. between secs. 2 and 35, from which
A Fir 16" dia., bears N.50°E., 11 lks. dist.
A Fir 36" dia., bears South, 27 lks. dist.

GLO survey by Elmer O. Worrick and Alonso Gesner, Deputy Surveyors, under Contract #659, dated May 21, 1896 - (DCSO records Vol. 7 Page(s) 2718-19)

The ¼ sec. cor., which is a Fir, 8" dia., mkd. ¼ S. on the N. side, from which
A Fir 20" dia., bears N.50°E., 11 lks. dist. mkd. ¼ S BT.
A Fir 36" dia., bears South, 27 lks. dist., mkd. ¼ S BT.

Donald L. Peel - For: Weyerhaeuser Co. - March 1967 - C.S. File 55/30-1

Found - 5" Fir mkd. ¼ on N. face, now 6" Fir snag, just a ring of bark. Scribe visible, but on South not North face.
36" Fir, South 27 lks., now 40" Fir, bark scribed, visible.
15" Fir N.50°E., 11 lks.; now 20" Fir snag, bark scribed, visible.
Removed shell of bark ½ ft. above ground and drove a 4 ft. x 3/4" pipe in the ground at the center of bark shell for new corner and re-referenced with "W" nails and Weyerhaeuser tags:
40" Fir S.1°W., 18.0 ft.
22" Fir N.18°E., 12.0 ft.