

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO records Vol. 7 Page(s) 2710)

-----  
Set Cedar post, 5 ft. long, 5 ins. dia., 20" in ground for the 1/4 sec. cor. between secs. 26 & 35, from which  
A Cedar, 10" dia., bears N.78°E., 64 lks.  
A Fir, 18" dia., bears N.23°W., 18 lks.

Elliott State Forest Corner Records by Federal Civilian Conservation Corp (CCC) 8/1933 - FB 119 Pg. 9 (Filed 4/24/1958 C.S. File 49/80)

-----  
No trace of OBTs (burn) at 27+50 ch. an 18" Cedar mkd. & blazed by Cruiser - 18 ft. No. of line.  
Set - 3"x3"x4' Fir post for 1/4 corner.  
20" Fir N.65°E., 44 ft.  
18" Fir N.39°E., 39 ft.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel - Mike Darby - Mike Stone - May & June 1964 - C.S. File 49/60

-----  
Found - D.Fir (now 42" dia.) N.65°E., 44.0 ft. scribing visible. 1933  
D.Fir (now 32" dia.) N.39°E., 39.0 ft. face open, but pitched over.

Set - Brass cap mkd: County Surveyors Office 1964 T23S R10W 1/4S26/S35  
6" Hemlock S.26°W., 24.7 ft. mkd: 1/4 S35 CS BT

Note - Found old, rotted Cedar stump scribed "1/4S" on E face S.33 1/2°W., 28.2 ft., which I believe to be an OBT - does not face right for call in government notes for BT - No other old tree found to match it, even if bearing given is in wrong quadrant.

**Corner renewed by me, is re-renewal of corner as set by Oregon State Bd. of Forestry only, not renewal of orig. corner.**

Fd. Ok by G. Miller, 6/10/1984 M 97-68