

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec. 2

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Levi C. Walker under contract #763, dated Aug. 23, 1905 - (DCSO records Vol. 7 Page(s) 2737)

Set a Fir post, 3 ft. long, 4' sq., 24" in the ground, for ¼ sec. cor. on S bdy of sec. 2, marked ¼ S2 on N face, from which

A Fir, 16" dia., bears S.44°E., 21 lks., mkd: ¼ S BT.

A Fir, 12" dia., bears N.34°E., 13 lks., mkd: ¼ S2 BT.

Arnold G. Gibson, Oregon St. Board of Forestry - Elbert Driver - Jan. 1958 - C.S. File 42/331

Found - Orig. fir post, now missing, point falls in cat road, from which;

16" Fir bears S.44°E., 21 lks., now 27" stump, scribes 1/ visible on exposed face.

12" Fir bears N.34°E., 13 lks., now 17" stump, pushed over in place, portion of scribes ¼ visible.

Set - 1½"x36" gal. iron pipe with 3" br. cap mkd: Ore. St. Bd. of Forestry ¼ S2 1957 RS359, 33" in ground, in mound of stone & from which a:

40" Fir bears N.20°E., 46.7 ft., scribed ¼ S2 BT.

36" Fir bears N.65°W., 36.5 ft., scribed RS359

James McIntosh, Oregon Dept. of Forestry - 7/2010 - M161-15

Found - OSBF 1½"x36" galvanized iron pipe & 3" bronze cap, 1958 (In place)

16" Fir (1906) S.44°E., 21 lks. (now 28"x3' high rotted stub in place, axe work visible)

12" Fir (1906) N.34°E., 13 lks. (missing)

40" Fir 1958) N.20°E., 46.7' (now 36"x3' high rotted stump in place, face rotted)

36" Fir 1958) N.65°W., 36.5' (now 36"x3' high rotted stump in place, axe work visible)

Rewitnessed -

17" Fir N.43°W., 14.0' to aluminum nail in BT face scribed (1/4S2BT) BT Tag

12" Fir N.04°E., 21.45' to aluminum nail in BT face scribed (1/4S2BT) BT Tag

Orange carsonite marker CBM-250 labeled WP N.28°W., 4.2' to base.

Orange carsonite marker CBM-250 labeled WP N.23°E., 3.1' to base.