

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T32-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 19 Page(s) 8246-47)

Set a Fir post 4½ ft. long, 4" sq., 24" in the ground for cor. to secs. 7, 12, 13 and 18, mkd. T32S S7 on NE.; R1W S18 on SE.; R2W S13 on SW.; and S12 on NW. faces, with 2 notches on N. and 4 notches on S. edges, from which
A Fir 35" dia., bears N.58°E., 29 lks. dist. mkd. T32S R1W S7 BT.
A Fir 3" dia., bears S.74°E., 23 lks. dist. mkd. T32S R1W S18 BT.
A Fir 4" dia., bears S.65°W., 7 lks. dist. mkd. T32S R2W S13 BT.
A Fir 14" dia., bears N.58°W., 7 lks. dist. mkd. T32S R2W S12 BT.

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747,, dated May 5,1902 - (DCSO records Vol. 19 Page(s) 8300)

Intersect E. bdy of Tp., 19 lks. N. of the cor. of secs. 7, 12, 13 and 18, which is a post, badly decayed and marks mostly all obliterated. The stumps of the SE. and SW. trees are standing. The NW. tree has fallen over. I reestablish this sec. cor. in the same place as follows:
Set a Fir post 6" sq., 3 ft. long for cor., marked T32S S7 on NE.; R1W S18 on SE.; S13 on SW.; and R2W S12 on NW. faces, with 2 notches on N. and 4 notches on S. edges, from which
A Fir 35" dia., bears N.58°E., 29 lks. dist. mkd. T32S R1W S7 BT.
A Fir 30" dia., bears S.50°E., 44 lks. dist. mkd. T32S R1W S18 BT.
A Fir 12" dia., bears S.31 3/4°W., 61 lks. dist. mkd. T32S R2W S13 BT.
A Fir 14" dia., bears N.29°W., 31 lks. dist. mkd. T32S R2W S12 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby & Wm. Stoffel, crew - Aug. 1963 - C.S. File 53/15

Found - Orig. 14" now 16" Fir stump, shows good reverse scribing, N.29°W., 20.5 ft.
Orig. 30" now 36" Fir snag S.50°E., 29.0 ft., shows good scribing.
Orig. SW. BT, not found.
Do find stump of orig. NE. BT.

(Cont. Next Page)

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T32-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set Brass cap at cor. mkd: County Surveyors Office
T 32 S
S 12 | S 7
R 2 W S 13 | S 18 R1W
1963

Logging road 75 ft. South.
New BTs- 5" Chinquapin bears N.38°W., 48.7 ft. scribed S12 CS BT.
12" Hemlock bears N.22°E., 49.6 ft. scribed S7 T32S R1W CS BT.
5" W.Fir bears S.86°E., 68.3 ft. scribed S18 CS BT.

Fd. OK, Aug. 1970, V. Tracy, DCSO - C.S. File 54/117

Survey by Glenn S. Baughman - For: U.S. Forest Service - Dec. 1976 - M 56-69; M 56-70 and M 56-68

Found - 1963 DCSO brass cap.
6" Chinquapin, dead, N.38°W., 48.7 ft.
20" W.Fir bears N.22°E., 49.6 ft.
36" Fir, snag, bears S.50°E., 29.0 ft.
6" W.Fir, stob, bears S.86°E., 68.3 ft.
New BTs- 10" Fir bears N.85°W., 23.3 ft. scribed "T32S R2W S13 BT" with brass washer "LS 536".
9" Fir bears S.34°E., 21.6 ft. scribed "T32S R1W S18 BT" with brass washer "LS 536".
10" Fir bears N.15°W., 62.3 ft. scribed "T32S R2W S12 BT" with brass washer "LS 536".

Survey by Glenn S. Baughman - For: U.S. Forest Service - July 1979 - C.S. File 58/176

Found - 1" Iron pipe, projecting 24" above the ground with a 2½" brass cap mkd. by the County in 1963.
35" D.Fir rotted stump, bears N.58°E., 19.1 ft.
6" Chinquapin snag with scribe marks "S12 CS BT" visible, bears N.38°W., 48.7 ft.
20" W.Fir with healed blaze bears N.22°E., 49.6 ft.
36" Fir, wind thrown snag, bears S.50°E., 29.0 ft.
12" D.Fir with scribe marks "T32S R2W S13 BT" visible on a partially healed blaze, bears N.85°W., 23.3 ft.
10" D.Fir with scribe marks "T32S R1W S18 BT" visible on a partially healed blaze, bears S.34°E., 21.6 ft.
10" W.Fir with scribe marks "T32S R2W S12 BT" visible on a partially healed blaze, bears N.15°W., 62.3 ft. (Cont. Next Page)

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T32-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs- 10" D.Fir bears S.72°W., 40.3 ft. I marked "T32S R2W S13 BT" on a double blaze and nailed a brass washer stamped "LS 536" into lower blaze.
12" D.Fir bears N.85°W., 23.3 ft. marked by Baughman in 1976. I chopped out "S13" and remarked "S12".

Survey by Lloyd R. Moffit - For: U.S. Forest Service - June 1985 - C.S. File 63/8

Found - 1963 DCSO brass cap on a 1" iron pipe.
18" Fir, dead, bears N.22°E., 49.6 ft. blazes healed
14" Fir bears S.34°E., 21.6 ft. scribe visible.
13" Fir bears S.72°W., 40.3 ft. scribe visible.
15" Fir bears N.85°W., 23.3 ft. scribe visible.
6" Fir, dead, bears N.37°W., 48.7 ft. scribe visible. (Rec. Chinquapin)
New BT - 7" Fir which bears N.01°E., 15.9 ft. scribed T32S R1W S7 BT.

John Ransom, USFS - Jonathan Drew - 9/2013 - C.S. 65/85-31

Found - 2½" brass cap (properly mkd) on 1" iron pipe, projecting 12" above a 3 ft diameter mound of stone.
19" Fir S.69½°W., 40.4 ft healed double blaze.
21" Fir N.85°W., 23.1 ft healed double blaze.
14" Fir N.7¼°E., 16.0 ft healed single blaze.
24" Fir S.32¼°E., 22.1 ft scribe on part. healed double blaze
Indt Fir stump N.27¾°W., 19.6 ft ax work on rotting stump
Indt root hole N.21½°E., 50.1 ft no log found.
Indt root hole N.38¾°W., 48.0 ft log with rotten face alongside
Indt root hole N.61¾°E., 19.5 ft some remains of stump found.

No new accessories established

Red paint applied to BT faces and a 6" band at head height, BTs include BT & survey monument tags
Note - Corner falls on north side of a graveled road, about 40 ft from centerline.
Measurements to accessories made with LEICA 1103+ Total Station with reflectorless EDM to aluminum nail set at side center, and to center of found root holes, basis of bearing being plat record bearing (S.89°51'50"W.) Using steel line post found about 80 ft west of corner.
Maintained line .5 miles east of corner. cont.

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Jonathan B. Drew, II, USFS - Assisted by: Andrew Hellman -
6/3/2015 - C.S. File 65/90-28

-
- Found - A 2½" brass cap on 1¼" galvanized iron pipe, projecting 12" above a mound of stone.
- Remains of an indt. Size fir stump bears, N.61°45'E., 19.5 ft, with no marks. (N.58°E., 19.1') 1883, (N.61°45'E., 19.5') 2013
- Remains of an indt. Size fir stump bears, N.27°45'W., 19.6 ft, with ax work, rec. (N.29°W., 20.5') 1902, (N.27°45'W., 19.6') 2013
- A root hole with rotted log alongside bears, N.38°45'W., 48.0 ft, rec. (N.38°W., 48.7') 1963, (N.38°45'W., 48.0') 2013
- A root hole bears, N.21°30'E., 50.1 ft, with no trace of log, rec. (N.22°E., 49.6') 1963, (N.21°30'E., 50.1') 2013
- A 21" fir bears, N.85°W., 23.1 ft, with a healed double blaze, rec (N.85°W., 23.3') 1976 (N.85°W., 23.1') 2013
- A 25" fir bears, S.32°15'E., 22.1 ft, with scribe on part. Healed double blaze, rec. (S.34°E., 21.6') 1976, (S.32°15'E., 22.1') 2013
- Remains of a rotten log with tags & no marks, no root hole found, rec. (N.15°W., - 62.3 ft) 1976 & 1979
- A 20" fir bears, S.69°30'W., 40.4 ft, with a healed double blaze, rec. (S.72°W., 40.3') 1979, (S.69°30'W., 40.4') 2013
- A 14" fir windfall bears, N.7°15'E., 16.0 ft, log lies west, rec. (N.1°E., 15.9') 1985, (N.7°15'E., 16.0') 2013

- New - A 16" fir bears, N.73°30'E., 5.7 ft, mkd "T32SR1WS7" "BT" on a double blaze.
- New BT includes ¾" brass washer mkd "ORPLS #89396" between B & T.

Corner maintenance/other info: clear brush from around monument and to BTs. Tie flagging to monument and guard posts, paint BT faces & a 6" band at head height, add new nails to existing BT tags & add new tags where needed.

Geodetic coordinates:
LAT: N. 42°47'47.126" LONG: W. 122°52'24.475"
Ellipsoid height - 3215 ft
Datum - WGS 84
Source - Cell phone GPS, for navigation to corner