

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 19 Page(s) 8249)

Set a basalt stone 15x12x12 ins., 10" in the ground for closing cor. to secs. 1 and 6, T32S R1W, mkd. CC on S. with 6 notches on S., E., and W. edges, from which

A Fir 15" dia., bears N.70°E., 11 lks. dist. mkd. C C T31S R1W S31 BT.

A Fir 55" dia., bears S.55°E., 5 lks. dist. mkd. CC T32S R1W S6 BT.

A Fir 35" dia., bears S.37°W., 15 lks. dist. mkd. CC T32S R2W S1 BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer - under special Instructions, dated June 7, 1922 - (DCSO records Vol. 18 Page(s) 7581)

Intersect the closing cor. of Tps. 32 S., Rs. 1 and 2 W., which is a basalt stone firmly set, 5x12x12 ins. above ground marked CC on S. with 6 notches on S., E., and W. edges; from which

A Fir 15" dia., bears N.70°E., 11 lks. dist. mkd. CC T31S R1W S31 BT (Old BT)

A Fir 55" dia., bears S.55°E., 5 lks. dist. mkd. CC T32S R1W S31 BT (Old BT)

A Fir 35" dia., bears S.37°W., 15 lks. dist. mkd. CC T32S R2W S1 BT. (Old BT)

Obliterate the marks on the old bearing tree in sec. 31.

Douglas Co. Surveyors Office - John M. Powell, Deputy - Frank Jones and W. Penley, crew - July 1968 - C.S. File 54/71

Found - Broken stone at township corner, no marks visible.
 55" D.Fir now 33" splintered stob, S.55°E., 3.3 ft., scribe visible.
 35" D.Fir now down and out of place, S.37°W., 9.9 ft. now root hole, found scribe CC T32S R2W.
 15" D.Fir now rotten stump, N.70°E., 7.3 ft.

Set Brass cap at cor. mkd: County Surveyors Office 1968

R	T 31 S	R
2	S 31	1
W	CC S 1 S 6	W
T 32 S		

New BTs- 32" D.Fir S.37°W., 33.6 ft. mkd. CC T32S R2W S1 CSBT
 32" D.Fir S.33°E., 26.2 ft. mkd. CC T32S R1W S6 CSBT
 Corner lies 15.8 ft. E. of ¼ cor. Sec. 31, T31-1.