

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 33 only, T31-1

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7461)

Set ¼ sec. post, from which
A Fir 30" dia. bears N.30°W., 14 lks. dist.
A Cedar 36" dia. bears S.15°W., 52 lks. dist.

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 18 Page(s) 7488)

The old ¼ sec. cor. on S. bdy. of sec. 33, which is a decayed post, with 1 BT still standing. I destroyed this post and replaced it with a basalt stone 14x10x8 ins. 10" in the ground mkd. ¼ on N. face, from which
A Cedar 40" dia., bears S.15°W., 52 lks. dist. mkd. ¼ S BT
A Fir 36" dia., bears N.3°E., 29 lks. dist. mkd. ¼ S BT.
The Cedar is the one described in field notes of original survey and was newly marked.

Douglas Co. Surveyors Office - John M. Powell, and crew - July/Aug. 1968 - C.S. File 54/71

Found - 14x10x8 corner stone mkd. with "¼" on the N. face. 40" now 46" Cedar S.25°W., 39.0 ft. (Rec. S.15°W., 34.3 ft.) shows scribing.
36" Fir now 38" stump, N.3°E., 19.1 ft., opened and found scribing "¼ BT"

Set Brass cap at cor. mkd: County Surveyors Office
T31S R1W ¼ S 33
T32S R1W 1968

New BTs- 14" Cedar N.54°W., 41.0 ft. mkd. ¼ S33 CS BT.
12" Fir N.42°E., 46.6 ft. mkd. ¼ S33 CS BT.
Cor. lies in S-W fence corner 150.1 ft. East of the sec. cor. to 4 & 5, T32-1W. and 300 ft. North of a road.

Fd. OK, Dec. 1992 by Kaiser - M 116-30