

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34 only, T31-1

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7461)

- 
- Set post cor. secs. 33, 34, 3 and 4, from which
- An Alder 36" dia., bears S.50°W., 50 lks. dist.
  - A Maple 12" dia., bears N.25°W., 30 lks. dist.
  - A Fir 15" dia., bears N.45°E., 45 lks. dist.
  - A Fir 24" dia., bears S.40°E., 45 lks. dist.

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 18 Page(s) 7487-88)

-----

The old sec.cor. to secs. 33 and 34, which is a decayed post with 3 BTs still standing. I destroyed this post and replaced it with a basalt stone, 18x9x7 ins., 12" in the ground for cor. to sec. 33 and 34 mkd. with 3 nooches on E. and W. edges, from which

- A Fir 28" dia., bears N.45°E., 45 lks. dist. mkd. T31S R1W S34 BT.
- A Maple 12" dia., bears N.25°W., 30 lks. dist. mkd. T31S R1W S33 BT.
- A Fir 40" dia., bears S.40°E., 45 lks. dist. mkd. T32S R1W S4 BT.

An Alder described in field notes or original survey has fallen. The three bearing trees were newly marked.

Arthur Boyer, Surveyor - Wit: Ted Schattenkerk - Sept. 1949 -C.S. File 40/214

-----

Found rock in place for this sec. corner; all four recorded trees are alive and all are as given in the recorded field notes except, the 40" Fir tree which is recorded as being S.40°E., 45 lks., which measures from the corner rock 36 lks. This tree is mkd. or scribed distinctly "S3". It is in sec. 4 not 3. This corner is of course for secs. 33 & 34 only and not for either 3 or 4.

Douglas Co. Surveyors Office - John M. Powell, and crew - July 25, 1968 - C.S. File 54/71

-----

Found - No trace of corner stone.

- 28" now 32" D.Fir, almost dead, N.45°E., 39.7 ft., shows good scar.
- 40" D.Fir, now burnt stob, S.40°E., faint burnt scribe visible.

(Cont. Next Page)

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 342700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34 only, T31-1

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

12" Maple, now dead, N.25°W., 19.8 ft., rotten face,  
old axe work and faint marks.  
This corner now lies on East edge of Elk Creek in dangerous  
place, therefore, SET WITNESS Corner 50.0 ft. East of Tree  
corner, mkd: County Surveyors Office 1968  
W.C. 50.0' West to T31S R1W  
S33 S34  
S 4  
T32S  
New BTs- 10" Ash S.6½°W., 11.4 ft. mkd. W.C. T32S R1W S4 CS  
BT.  
9" Ash N.66°W., 16.8 ft. mkd. W.C. T31S R1W S34 CS  
BT.  
This cor. lies on top of creek bank 2.50 ft. South of fence  
line.