

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated Sept. 1856 (DCSO DLC records Page 41)</p> <p>-----</p> <p>Set post SE cor., from which An Oak 18" dia., bears S.8°W., 229 lks. An Oak 36" dia, bears S.28°E., 375 lks.</p>	
<p>Wilford Haines - For: C. Soloman - June 18, 1962 - M 23-76</p> <p>-----</p> <p>Found - 40" Oak S.08°W., 229 lks. has been rescribed BT. Hole for 36" Oak S.28°E., 375 lks.</p>	
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 10/3/2001 - C.S. File 66/29-16</p> <p>-----</p> <p>Found - 1" square head bolt with a 3" dia., washer protrudes 1" above ground (source unknown) (Similar bolt's set in 1914 Vol. 5 Pg. 20) Corner of 2½ ft. West of a N'y - S'y fence. 18" now 33" dia., down W.Oak previously opened rotted blaze, we open lower & find orig. reverse scribing "T" approx. 9" from center of tree, root hole bears S.8°W., 151.1 ft. (Haines 1962 M23-76 survey notes this BT as having been rescribed, 1949 D.C. Rd 203 survey shows tie to DLC corner and this BT)</p> <p>New - 5/8" iron rod in a 4-way fence corner set M 42-43 bears S.10½°W., 94.7 ft. (compass decl. 17½°E. agrees well with M 42-43) 5/8" iron rod set in M42-43 at a fence corner bears, N.12¼°E., 115.1 ft. 16" dia., D.Fir double blazed & scribed "SE DLC 37 CS BT" bears N.24¾°E., 83.1 ft. 19" dia., D.Fir double blazed & scribed "SE DLC 37 CS BT" bears S.30°W., 13.2 ft. 13" dia., D.Fir double blazed & scribed "SE DLC 37 CS BT" bears N.7°W., 8.6 ft.</p> <p>Set - 2 3/8" dia., brass cap on a 1 3/8" O.D. by 32" long iron pipe at referenced position of bolt. BC/IP protrudes 5" above ground. 29" long 3/4" dia., bolt set along south edge of BC/IP protrudes 3" out of ground. Cap marked: DOUGLAS COUNTY SURVEYORS OFFICE T 22 S SE R 7 W DLC 37 2001</p>	
<p>FD. BC by D. Edwards, 1/2013 - M164-55 Fd. BC & BTs by C. Sweeden 10/2016 - M172-63</p>	