

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1525)

-----  
Set ¼ sec. post, from which  
A Fir 40" dia., bears N.38°E., 33 lks. dist.  
A Fir 48" dia., bears N.20°W., 17 lks. dist.

Wilford N. Haines, #239 - For: Woolley Logging Co. - Dec.1963  
M 27-16

-----  
Set 1" x 1" x 36" T Iron, from which, scribed  
6" W.Fir S.5°W., 2.9 ft.  
6" W.Fir N.88°E., 21.8 ft.

Wilford N. Haines, #239 - For: May 30, 1965 - C.S. File  
51/309

-----  
Found T Iron in place. Both BTs gone.  
New BTs -8" D.Fir N.71°W., 40.0 ft.  
5" W.Fir N.15°E., 48.9 ft.

Troy Rambo - For: Seneca Jones Timber - Mar. 2004 - M144-19

-----  
Found - "T" iron per M27-60  
Did not find the rec. BTs.  
New - Scribed "¼ S8 BT" on 9" DF - bears N.11°W., 11.0 ft.  
Scribed "¼ S8 BT" on 10" DF - bears S.66°W., 11.5 ft  
Scribed "¼ S9 BT" on 12" DF - bears S.76°E., 18.3 ft  
Scribed "¼ S9 BT" on 11" DF - bears S.40°E., 13.5 ft

Harvey Christensen - For: Seneca Jones Timber Co. - Aug. 2006  
- M151-45

-----  
Found - 1" "T" rod w/o brass cap (Haines) 0.8 ft above  
grade.  
16" W.Fir N.15°E., 48.9 ft, healed face, Haines  
9" D.Fir N71°W., 40.0 ft. 1" stump scribing visible,  
Haines  
CS M144-19 (Rambo) BTs were also found as described.  
Haines proportioned corner is N.28°51'E., 9.6' from mid point  
& 4.5" east of the section line. Upon searching for the  
original corner a 48' D.Fir 3' stump was located with partial  
face & accepted for evidence of the original NE BT. A small  
depression was found at the location of the NW BT position.  
Distance to creek CL was within acceptable limits (2.1 ch)

continued next page

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set - A 2.5" aluminum cap was set on a 5/8"x30" rebar stamped "NTCI LS 2603" record bearing & distance from the face of said fd stump (S.38°W., 21.8 ft) Additional bearing trees added as follows, not suitable trees available in clear cut to SW.  
14" D.Fir north, 22.7 ft. blazed & scribed "¼ S8 BT"  
10" D.Fir N.26°E. 19.8 ft blazed & scribed "¼ S9 BT"  
17" W.Fir S.15°E. 32.6 ft blazed & scribed "¼ S9 BT"

Note - Corner falls 40' north of road, 140' (2.1 ch.) (2.5 ch record) north of CL creek.