

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO records Vol. 7 Page(s) 2710)

Set a Cedar post, 5 ft. long, 5 ins. dia., 20" in ground for the ¼ sec. cor. between secs. 34 & 35, from which
 A Cedar, 10" dia., bears N.78°E., 64 lks.
 A Fir, 18" dia., bears N.23°W., 18 lks.

Fd. Ok on GLO resurvey and retracement by Levi C. Walker under contract #763, dated Aug. 23, 1905 - (DCSO records Vol. 7 Page(s) 2750)

Douglas Co. Surveyors Office - Gary Langlitz - Pete Earle - Feb. 13, 1975 - C.S. File 57/17-19

A diligent search of the area was made, based on a request from the Coos Bay District of BLM. Several trees in the vicinity have been previously opened. We check the work previously done and open some of the trees further. We find apparent cruiser's marks on one tree which are approx. 40 years old. We don not find any evidence of orig. BT marking.
We do not monument this corner.