

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 35 & 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO recs. Vol. 7 Page(s) 2701)

Set a cherry post, 4 ft. long, 6" dia., 18" in ground for the 1/4 sec. cor. between secs. 35 & 36, from which
 A fir, 14" dia., bears S.30°E., 18 lks.
 A fir, 16" dia., bears N.65°W., 24 lks.

BLM corner card on file at Coos Bay District Office, H. Walitalo head chainman & C. Sartz compassman, dated 11/18/1971, rec'd and filed by DCSO 7/14/2015 - C.S. 65/89-10

I placed a steel fence post, from center of bearing tree, BT, bearing S.65°E., dist. 16'. On steep hillside midway between a ridge and a creek. BT tag posted.

Tony Hostetter - For: Weyerhaeuser - May 2015 - C.S. 65/88-9

Found - Steel fence post set by BLM in 1971. Local record card in North Bend BLM Office indicates a 30" Fir, N.65°W., 16.0' was used to set post. (GLO: N.65°W., 24 lks) from which:
42" Fir stump, BT tag, bears; N.60°E., 24.0 ft.
14" Fir, scribed "S36 1/4 BT", BT tag, bears; S.56°E., 17.0 feet to spike.
12" Fir, scribed "S35 1/4 BT", BT tag, bears; S.60°W., 13.6 feet to spike.
5" Fir, scribed "S35 1/4 BT", BT tag, bears; N.64°W., 4.5 feet to spike.