

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12 only, T23-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 6 Page(s) 2631-32)

-----  
Set a Laurel post 36 x 4, 18" in ground for the corner to Secs. 1, 6, 7 and 12, from which  
A Laurel 5" dia., bears N.2°E., 7 lks. dist.  
A Laurel 5" dia., bears S.75°E., 12 lks. dist.  
A Laurel 5" dia., bears S.30°W., 30 lks. dist.  
A Laurel 5" dia., bears N.20°W., 45 lks. dist.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #688 dated May 21, 1896 (DCSO records Vol. 7 Page(s) 2696)

-----  
(Page 2696)  
The old cor., which is a Laurel post, 4" sq., 30" high, badly decayed, mkd. and witnessed as described by the Surveyor General. Cor. falls in a burn and the post with its bearing trees are burned up. I destroyed all marks referring on sec. 6.

A.R. Evans - Wit: J.E. Clinton and P. Duckett - Feb. 1952 - C.S. File 41/6

-----  
Found Orig. BT, Laurel N.20°W., 45 lks.  
Set 4" x 4" x 36" Fir stake. Blazed and scribed new BTs:  
24" Fir S.72°W., 21.4 ft., mkd. S12 T23S R10W RE 2741 BT  
12" Fir N.10°W., 31.4 ft., mkd. S1 T23S R10W BT.

Fd. OK, July 1967 by A. Gibson - M 36-32  
Fd. OK, Sept. 1968 by Wm. Stiles - M 36-42

BLM resurvey by James E. Jelley and Rolla R. Steward, Cadastral Surveyors under Group # 703, surveyed July 1969/May 1970 (DCSO records Vol. 35 Page(s) 14549-50)

-----  
The Sec. Cor., perpetuated and recorded by the County in 1952, monumented with the point of a wooden stake, 18" below the surface of ground, from which the remaining original bearing tree:  
A Laurel 15" dia., bears N.20°W., 45 lks. dist., with healed blaze.  
and bearing trees mkd. by the County in 1952:  
A Fir 23" dia., bears S.72°W., 32 lks. dist., with fragmentary scribe marks visible on opened blaze.  
A Fir 15" dia., bears N.12 3/4°W., 43 lks. dist. mkd. with fragmentary scribe marks visible on opened blaze.  
(Cont. Next Page)

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 700600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12 only, T23-10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,  
with brass cap mkd:

T 23 S	T 23 S
S 1	R 9 W
S 12	S 7
R 10 W	

1970

BLM resurvey by Joseph M Mannix & Edith M Forkner, Cadastral Surveyors Under group No. 2727 surveyed Oct. 2013/April 2014 - (DCSO records Vol. 58 Page(s) 23215-16)

-----  
The cor. of secs. 1 & 12; monumented with an iron post, 2½" dia., firmly set, with top flush with the surface of the ground, with a brass cap (properly) mkd.

from which the remains of bearing trees mkd. by Evans in 1952  
A fir high stump, 28" dia., bears S.72°W., 21.1 ft., with a healed double blaze.

A fir, 28" dia., bears N.12¾°W., 28.4 ft., with a healed blaze at breast height.

and a new bearing tree

A fir, 4" dia., bears S.62½°W., 30.0 ft., mkd. X BT.

Corner is located on the NE cor. of fir reproduction, edge bears S & W.

From the corner

S.1°34'12"E., 50 ft., spur, slopes West.

Each new bearing tree has a 2½"x1/4" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.

Each new corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.

An aluminum angle iron, 5 ft. long, was driven alongside all corners unless an existing guard post was otherwise noted in the corner description.