

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Rufus S. Moore, Deputy Surveyor, under contract 475 dated July 3, 1883 - (DCSO records Vol. 19 Page(s) 8263)

-----  
Set a fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on N side; from which

A fir, 10" dia., bears N.22°W., 20 lks., mkd: ¼ S BT.

A fir, 14" dia., bears S.12°W., 15 lks., mkd: ¼ S BT.

BLM Dependent resurvey by Hans W Thielsen, under Group #318, surveyed Aug/Sept 1955 - (DCSO records Vol. 28 Page(s) 12136)

-----  
Point for the ¼ sec. cor. of secs. 10 & 15, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 36 long, 1" dia., 24" in the ground to solid rock & in a mound of stone to top, with brass cap mkd

¼  $\frac{S\ 10}{S\ 15}$   
1955

from which

A fir, 50" dia., bears S.13½°W., 47 lks., mkd: ¼ S15 BT.

A fir, 14" dia., bears N.48°W., 110 lks., mkd: ¼ S10 BT.

Gerald Nygren - For: USFS - July 1989 - C.S. File 63/85

-----  
Found - USGLO 1955 1" iron pipe with 2½" brass cap extended 10" above stone mound and marked properly.  
19" dia. D.Fir stump, N.48¼°W., 72.3 ft. (N.48°W., 72.6 ft. Rec.)

50" dia. D.Fir, S.16½°W., 30.5 ft. (healed blaze) (S.13½°W., 31.0 ft)

(Note - Above monument (iron pipe) has been bent.)

New BT - A 7" dia. D.Fir N.2°E., 28.2 ft. scribed "¼ S10 BT".  
Nailed ½" brass washer marked "LS 1035" to lower blaze.