

PRIMARY CORNER DESCRIPTION Cor. Secs. 28, 29, 32, & 33

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. Thiel under contract 260 dated April 17, 1877 - (DCSO records Vol. 1 Page(s) 309)

-
- Set post to secs. 28, 29, 32, & 33; from which
- A Cedar, 42" dia., bears S.51 $\frac{3}{4}$ °E., 51 lks.
 - A Fir, 42" dia., bears N.25 $\frac{3}{4}$ °E., 1.26 chs.
 - An Alder, 30" dia., bears N.17 $\frac{1}{2}$ °W., 68 lks.
 - A Maple, 12" dia., bears S.85 $\frac{1}{2}$ °W., 94 lks.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12506)

The cor. of secs. 28, 29, 32, & 33, falls in roadway, determined at the rec. bearing & dist. from each of the remaining orig. BTs, as follows:

- A fir stump, 72" dia., bears N.25°45'E., 126 lks., with partly burned & decayed blaze facing corner.
- A cedar stump, 84" dia., bears S.51°45'E., 51 lks., with no marks remaining on badly decayed face of old blaze. This stump has now been removed during clearing operations for access road.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 48" in clay sub-grade of access road, with brass cap marked:

T20S R9W
S 29|S 28
S 32|S 33
1953

from which new BTs & reference monuments,

- A fir, 40" dia., bears N.44 $\frac{1}{4}$ °E., 122 lks., mkd: T20S R9W S28 BT.
- An iron post, 3 ft. long, 2" dia., set 28" in the ground, for a reference monument, bears N.45°E., 90 lks., with brass cap marked T20S R9W S28 RM 1953 & and arrow pointing to the corner.
- A fir, 38" dia., bears S.73 $\frac{1}{2}$ °E., 106 lks., mkd: T20S R9W S33 BT.
- An iron post, 3 ft. long, 2" dia., set 28" in the ground, for a reference monument, bears S.45°W., 90 lks., with brass cap marked T20S R9W S32 RM 1953 & and arrow pointing to the corner.
- A fir, 28" dia., bears S.50°W., 83 lks., mkd: T20S R9W S32 BT.
- A fir, 31" dia., bears N.13°45'W., 175 lks., mkd: T20S R9W S29 BT.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 28, 29, 32, & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM remonumentation of Orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 37 Page(s) 15388) - Fd. BC & 6 BOs - Set a 6' steel fence post alongside the iron post.

BLM dependent resurvey by Owen C. Chatters II, Cadastral Surveyor, under Group #777, surveyed May/June 1972 - (DCSO rec. Vol. 36 Page(s) 15009)

The cor. of sec. 28, 29, 32, & 33, determined at record bearing & dist. from the remains of the orig. BTs

A fir stump, 45" dia., bears N.25³/₄°E., 126 lks., with healed blaze.

and BTs & reference monuments mkd. by Tillman & Gawron

A fir, 47" dia., bears N.44¹/₂°E., 122 lks., with healed blaze.

An iron post, 2" dia., firmly set protruding 6" above ground, bears N.45°E., 90 lks., with brass cap marked T20S R9W S28 RM 1953 & and arrow pointing to the corner alongside of which a steel fence post, firmly set, protruding 4 ft. above ground.

A fir, 50" dia., bears S.73¹/₂°E., 106 lks., with healed blaze.

An iron post, 2" dia., firmly set protruding 6" above ground, bears S.45°W., 90 lks., with brass cap marked T20S R9W S32 RM 1953 & and arrow pointing to the corner.

A fir, 34" dia., bears S.50°W., 83 lks., with healed blaze.

A fir, 37" dia., bears N.7°W., 175 lks., with healed blaze. (Rec. N.13³/₄°W.)

and a BT of which I have no rec.

A fir, 45" dia., bears N.84³/₄°E., 129 lks., with healed blaze.

At the corner point
Drive a concrete nail, 1¹/₂" long, ¹/₄" dia., head into asphalt roadway, with head flush with surface.

FD. Ok by Eimstad, Aug. 1981 - M 89-13

Les Roberts, LS 1039 - Nov. 14, 1987 - C.S. File 63/50

Note - Corner previously referenced out Nov. 4, 1985. See C.S. 63/50 for reference notes.

CORNER REPORT
Found - NE reference monument has been up-rooted by recent logging activity. continued next page

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Cor. Secs. 28, 29, 32, & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

1953 GLO brass cap RM bears S.44°53'45"W., 59.04 ft.
37" Fir, S.49½°W., 54.5 ft. (scar vis.) 1953 BT rec.
S.50°W., 54.8 ft.
40" Fir stump, N.06°W., 115.5 ft. (scar vis) 1953 BT
Rec. N.13¼°W., 115.5 ft.
49" Fir stump, S.73½°E., 70.0 ft. scar vis. 1953 BT
rec. S.73½°E., 70.0 ft.
49" Fir stump, N.84½°E., 84.7 ft. scar vis. No rec.
54" Fir stump, N.44½°E., 80.4 ft. 1953 BT. Rec.
N.44¼°E., 80.5 ft.
Re-set - NE reference monument using "PK" nail R.P.'s set on
11/4/1985. Buried purple magnetic marker under
iron pipe.
Set metal fence post, with land survey monument sign
attached to, beside brass cap.