

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 10, & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel under contract 567 dated Feb. 16, 1891 - (DCSO records Vol. 1 Page(s) 349-50)

A fir, 20" in dia., which I marked T20S S2 on NE R9W S11 on SE, S10 on SW, S3 on NW sides, with 5 notches on S & 2 notches on E sides, for cor. to secs. 2, 3, 10, & 11; from which

A fir, 30" dia., bears N.73°E., 22 lks., mkd: T20S R9W S2 BT.

A fir, 24" dia., bears S.20½°E., 15 lks., mkd: T20S R9W S11 BT.

A fir, 30" dia., bears S.86°W., 27 lks., mkd: T20S R9W S10 BT.

A vinemaple, 6" dia., bears N.17°W., 7 lks., mkd: T20S R9W S3 BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated April 8, 1920, Group 56 - (DCSO records Vol. 1 Page(s) 383)

Intersect the cor. of secs. 2, 3, 10, & 11, originally a fir, 20" dia., now dead and uprooted, marked & witnessed as described by the surveyor general, except that the NE & SE BTs are dead & down, & the NW BT is dead. At exact corner point, in cavity of uprooted corner tree.

Set an iron post, 3 ft. long, 2" dia., 26" in the ground, for cor. of secs. 2, 3, 10, & 11, with brass cap marked

T20S	R9W
S 3	S 2
S 10	S 11
1921	

from which

(New BT) A vine maple, 4" dia., bears N.34°E., 28 lks., mkd: T20S R9W S2 BT.

(New BT) A chittem, 5" dia., bears S.63°E., 56 lks., mkd: T20S R9W S11 BT.

(Old BT) A fir, 36" dia., bears S.86°W., 27 lks., mkd: T20S R9W S10 BT.

(New BT) A fir, 30" dia., bears N.42°W., 42 lks., mkd: T20S R9W S3 BT.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12492-3)

The cor. of secs. 2, 3, 10, & 11, remonumented by Fred Mensch, in 1921, with an iron post, 2" dia., 16" above ground firmly set, with brass cap (properly) marked: cont. next pg

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 10, & 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

from which

A vine maple, 6" dia., bears N.34°E., 28 lks., with partial scribe marks visible on nearly healed blaze. (Mensch BT)

An uprooted fir, 44" dia., plainly blazed & healed, the stump hole of which bears S.86°W., 27 lks. (Thiel BT)

An uprooted fir, 38" dia., plainly blazed & healed, the stump hole of which bears N.42°W., 42 lks. (Thiel BT)

Reset the iron post, now 8" above ground, & mark additional BTS as follows:

A fir, 40" dia., bears S.4¼°E., 38 lks., mkd: T20S R9W S11 BT.

A fir, 27" dia., bears S.66°45'W., 56 lks., mkd: T20S R9W S10 BT.

A fir, 28" dia., bears N.59°W., 70 lks., mkd: T20S R9W S3 BT.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23097-8)

The cor. of secs. 2, 3, 10, and 11, monumented with an iron post, 2" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd.

from which the remains of an original bearing tree

A roothole bears S.86°W., 17.8 ft. with decayed fir remains alongside, no marks visible.

and the remains of a BT mkd. by Mensch in 1921-22

A roothole bears N.42°W., 27.7 ft., with a down fir stump, 36" dia, lying alongside, no marks visible.

and the remains of the bearing trees mkd. by Tillman and Gawron in 1953-54

A roothole bears S.4¼°E., 25.1 ft., with a down fir, 40" dia., alongside, no marks visible.

A roothole bears N.59°W., 46.2 ft., with a down fir, size indeterminate, alongside, no marks visible.

and new bearing trees

A chinquapin, 4" dia, bears N.78°E., 12.8 ft., mkd. X BT.

A fir, 9" dia, bears S.2½°E., 21.9 ft., mkd. T20S R9W S11 BT.

A fir, 13" dia, bears S.53°W., 3.4 ft., mkd. T20S R9W S10 BT.

A fir, 5" dia, bears N.23°W., 5.5 ft., mkd. X BT.

An iron pipe, 2" dia, firmly set, projecting 2" above ground, with concrete core cor., established by person(s) unknown, is alongside the cor.

Cont.

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 10, & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ronald L Rice - Oct. 2016 - Oxbow Timber 1 LLC - M172-65

Found - 1921 GLO brass cap with the following accessories:
5" Chinquapin bears N.78°E., 12.8', bark scribed visible.

13" D.Fir bears S.2½°E., 21.9', healed face.

18" D.Fir bears S.53°W., 3.4', healed face.

7" D.Fir bears N.23°W., 5.5', healed face.

2" iron pipe with concrete cor. alongside 1921 GLO corner monument. Steel post adjacent to corner.