

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Corner Secs. 15 & 16

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

LO survey by Levi C. Walker under contract #763, dated June 20, 1905 - (DCSO records Vol. 7 Page(s) 2731)

-----  
Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S16 on W and 15 on E faces; from which  
A Fir, 10" dia., bears S.30'E., 79 lks., mkd: ¼ S15 BT.  
A Fir, 8" dia., bears N.67°W., 69 lks., mkd: ¼ S16 BT.

Arnold G. Gibson, Oregon St. Board of Forestry - 12/16/1968 - C.S. File 55/101

-----  
Found - Orig. post missing, from which a:  
10" Fir bears S.0½°E., 79 lks., now 39" stump, in place, scribe visible.  
8" Fir bears N.67°W., now 36" stump, in place, face open, no scribe visible.  
Set - 1½"x36" galv. IP with 3" br. cap mkd: Ore. St. Bd. of Forestry ¼ S15 S16 1969 RS359, 34" in ground, and from which a:  
14" Fir bears N.83½°E., 25.4 ft., to face, scribed ¼ S15 BT RS359.  
14" Fir bears N.30°W., 23.9 ft., to face, scribed ¼ S16 BT.  
Ore. St. Bd. of Forestry metal location poster on orig. 14" Fir BT N.30°W.  
4"x4"x72" white painted cedar post 1.4' S.50°W. of pipe

Please note that this corner is on the Douglas Co. & Coos Co. line and Coos Co. Surveyor's Office may have more information concerning this corner.