

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Levi C. Walker under contract #763, dated June 20, 1905 - (DCSO records Vol. 7 Page(s) 2733)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S10 on N and 15 on S faces; from which
A Fir, 10" dia., bears S.7°E., 30 lks., mkd: ¼ S15 BT.
A Fir, 10" dia., bears N.48°W., 85 lks., mkd: ¼ S10 BT.

Arnold G. Gibson, Oregon St. Board of Forestry - Charles W. Cook - May 30, 1972 - C.S. File 55/233

Found - Orig.. post missing from which a:
10" Fir bears S.7°E., 30 lks., now 52" stump in place, face grown over.
10" Fir bears N.48°W., 85 lks., now 42" stump in place, exposed scribes 1/
Set - 1½"x36" galv. IP w/3" bronze cap mkd: OREGON STATE BOARD OF FORESTRY ¼ S10 S 15 1971 RS 359, 34" in ground, and from which a:
19" Fir, bears S.56½°E., 77.6 ft., to face; scribed ¼ S15 BT RS 359.
15" Fir, bears N.62°E., 62.5 ft., to face; scribed ¼ S10 BT.
4"x4"x72" white painted Cedar post 4.5 ft. N.45°W., of corner pipe.
Oregon St. Forestry Dept. metal location poster on 19" Fir BT S.56½°E., 77.6 ft.