

PRIMARY CORNER DESCRIPTION Cor. Secs. 14 & 23 (West)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO records Vol. 7 Page(s) 2712)

Set a Fir post, 5 ft. long, 5 ins. dia., 20" in the ground for the corner to secs. 14, 15, 22 & 23, from which
A Fir, 60" dia., bears N.30°E., 8 lks.
A Fir, 24" dia., bears S.45°E., 154 lks.
A Fir, 60" dia., bears S.45°W., 6 lks.
A Fir, 50" dia., bears N.55°W., 36 lks.

GLO resurvey and retracement by Levi C. Walker under contract #763, dated Aug. 23, 1905 - (DCSO records Vol. 7 Page(s) 2729-30)

Intersect N & S line, 1.57 chs., N.0°12'W. of cor. of secs. 14, 15, 22, & 23, which is a Fir post, 4" sq. 12" above ground, badly decayed, marked and witnessed as described by the Surveyor General.
I destroy old post & obliterate all marks referring to secs. 15 & 22 on BTs and at the same point
Set a new Fir post, 3 ft. long, 4" sq. 24" in the ground mkd: T23S S14 on NE, and R10W S23 on SE face, with 3 notches on S & 2 notches on E. edge.
The intersection being beyond allowable closing limits.

Arnold G. Gibson, Oregon St. Bd. of Forestry - May 1970 - C.S. File 55/154

Found - Orig. Fir post destroyed by Levi Walker in 1906) from which a
60" Fir bears N.30°E., 8 lks., now 60" stump in place, bottom of face with axe work visible.
24" Fir S.45°E., 154 lks., now 40" stump in place, old axe work visible.
60" Fir bears S.45°W., 6 lks., (obliterate by Levi Walker) now 55" stump in place.
50" Fir bears N.55°W., 36 lks., (obliterate by Levi Walker) now missing, point falls in old cut road.
Restoration by Levi Walker in 1906
Fir post missing from which a
Closing corner 15 & 22 bears N. 1.57 chs., in place.
Set - 1½"x36" galv. IP with 3" bronze cap mkd: "Ore. St. Bd. of Forestry T23S S14 S23 S22 R10W1970 RS359", 34" in ground at corner point & from which a:

continued next page

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Cor. Secs. 14 & 23 (West)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

8" Fir bears N.82°E., 11.4 ft. to face; scribed T23S R10W S14 BT RS359.
5" Fir bears S46°E., 68.1 ft. to face; bark scribed T23S R10W S23 BT.
4"x4"x72" White painted Cedar post 1.3 ft. N. of corner pipe.
Ore. St. Forestry Dept. metal location poster on 8" Fir BT N.82°E., 11.4 ft.

James M McIntosh - For: Oregon Dept. Of Forestry - March 1999
- M 131-44

Found - Oregon St. Board of Forestry 1½" x 36" galv. IP/3" bronze cap, 1970
60" Fir (1879) N.30°E., 8 lks., now 60"x2' high rotten stump, some axe work visible.
24" Fir (1879) S.45°E., 154 lks., now 40"x2' high rotten stump, old axe work visible.
60" Fir (1879) S.45°W., 6 lks., obliterated by Levi Walker, now 55"x2' high rotten stump
8" Fir (1970) N.82°E., 11.4 ft., yellow metal location poster, now 17", face closed.
5" Fir (1970) S.46°E., 68.1 ft., now 15", bark scribes visible.
Set - Orange Carsonite markers, CBM-25OR labeled WP, bears:
N.47°E., 3.0 ft to base.
S.26°E., 2.3 ft. to base.