

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, & 15 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO records Vol. 7 Page(s) 2713-14)

Set a Fir post, 5 ft. long, 5 ins. dia., 20" in the ground for the corner to secs. 10, 11, 14 & 15, from which
A Fir, 10" dia., bears N.23°E., 95 lks.
A Fir, 50" dia., bears S.45°E., 72 lks.
A Fir, 20" dia., bears S.75°W., 54 lks.
A Fir, 8" dia., bears N.15°W., 131 lks.

GLO resurvey and retracement by Levi C. Walker under contract #763, dated Aug. 23, 1905 - (DCSO records Vol. 7 Page(s) 2734-5)

Set a Fir post 3 ft. long, 4" sq., 24" in the ground, for cor. of secs.11 & 15, marked T23S S11 on SE., R10W S15 on SW face, with 4 notches on S., & 2 notches on E. edge; from which
A Fir, 24" dia., bears S.9°E., 85 lks., mkd: T23S R10W S11 BT.
A Fir, 24" dia., bears S.57°W., 63 lks., mkd: T23S R10W S15 BT.

Arnold G. Gibson, Oregon St. Board of Forestry - Charles W. Cook - 10/13/1972 - C.S. File 55/274

Found - Orig. post missing from which a:
24" Fir bears S.9°E., 85 lks., now 63", in place, face burned away.
24" Fir bears S.57°W., 63 lks., now 46", in place, exposed scribed T and parts of back cast on burnt face.
Closing corner 15 & 22 bears N. 1.57 chs., in place.
Set - 1½"x36" galv. IP with 3" bronze cap mkd: "Ore. St. Bd. of Forestry T23S S10 S15 S11 R10W1970 RS359", 34" in ground at corner point & from which a:
13" Fir bears S.26½°W., 76,2 ft. to face, scribed T23S T10W S15 BT RS359.
56" Fir bears S.84°E., 40.1 ft. to face, scribed T23S R10W S11 BT.
4"x4"x72" white painted Cedar post 2.6 ft. S.64°E., of corner pipe.
Oregon St. Forestry Dept. metal location poster on 56" Fir BT S.84°E., 40.1 ft.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, & 15 only

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Arnold G. Gibson, St. of Oregon, Dept. of Forestry -
Witnessed by James M. McIntosh - June 14, 1976 - C.S. File
58/31

Found - Orig. post missing from which a:
24" Fir bears S.9°E., 85 lks., now 63" stump in
place, face burned away.
24" Fir bears S.57°W., 63 lks., now 46", in place,
scribes T and parts of back cast on burnt face
exposed.

Restoration by A. Gibson, 1972

Found - 1½"x36" GIP, in place, from which a:
13" Fir bears S.26½°W., 76,2 ft. missing, in new cat
road location.
56" Fir bears S.84°E., 40.1 ft. now 56" stump, in
place, scribes T23S R10W S11 BT visible.
4"x4"x72" WPCP bears S.64°E., 2.6' found in place.

Re-witnessed from above 1½"x36" GIP. a:
57" Fir stump bears S.87°W., 15.8 ft. to face,
scribed T23S R10W S15 RS359.
63" Fir stump (orig.) bears S.9°E., 55.0' to face,
scribed T23S R10W S11 BT.
Oregon St. Forestry Dept. metal location poster on
4"x4"x72" WPCP S64°E., 2.6 ft.

Oregon Dept. of Forestry, James McIntosh - Witness: Ralph C.
Hall - Sept. 26, 2000 - C.S. File 65/33-3

Found - 24" Fir S.9°E., 85 lks.: now 39"x3' high rotted
stump in place, no marks visible.
24" Fir S.57°W., 63 lks.: now 52"x3' high rotted
stump in place, scribe T visible on exposed face.
Oregon State Board of Forestry 1½"x36" galvanized
iron pipe with 3" bronze cap,
13" Fir S.26½°W., 76.2 ft., from 1972 - missing.
56" Fir S.84°E., 40.1 ft., now 48"x4' high stump in
place face rotted, axe work visible on bark. 1972
4"x4"x72" white painted cedar post S.64°E., 2.6 ft.,
now rotted & fallen over. 1972

57" Fir stump S.87°W. 15.8' now 54"x3' high rotted
stump in place, scribes vis. on rotting face. 1976
New - 11" Fir S.59°E., 25.5' to alum. nail in BT face
scribed T23S R10W S11 BT. BT tag.

Carsite witness post S.43°E., 3.65' to base
8" Fir S.26°W., 3.4 ft. to alum. nail in BT face
scribed T23S R10W S15 BT. BT tag.

Note - Magnetic variation set at 20°E.