

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 10 only (East)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Levi C. Walker under contract #763, dated Aug. 23, 1905 - (DCSO records Vol. 7 Page(s) 2735)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. on E bdy. of sec. 10, marked ¼ S10 on W face; from which

A Fir, 7" dia., bears N.52°E., 254 lks., mkd: ¼ S BT.

A Fir, 20" dia., bears S.20°45'W., 254 lks., mkd: ¼ S10 BT

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - S. Bilow - For: "West Shore Lodges Subdivision, Mr. Rose & Mr. Lee - Feb/May 1958 - M 8-72 & C.S. File 49/90

Found - Both orig. BTs & bottom section of wood stake at corner.

Also check bearing & distance to large rotted snag recorded as line tree 33.0 ft. North of corner.

I do not open either BT., show good scars.

The SW BT now 56" Fir. This BT same tree used for W ¼ corner sec. 10.

New BTs- 20" R.Fir bears N.11°W., 46.7 ft. scribed ¼ S10 CS BT.

18" R.Fir bears S.82½°W., 41.8 ft. scribed ¼ S10 CS BT.

Set - Brass cap mkd: E ¼ S10 T23S R10W County Surveyors Office 1958.