

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #292, dated August 7, 1878 - (DCSO recs. Vol. 7 Page(s) 2703)

Set Maple post, 4 ft. long, 5 ins. dia., 18" in ground for the ¼ sec. cor. between secs. 25 & 26, from which
A Maple, 12" dia., bears East, 57 lks.
A Fir, 40" dia., bears West, 70 lks.

Elliott State Forest Corner Records by Federal Civilian Conservation Corp (CCC) 8/16/1933 - FB 119 Pg11

No trace of ¼ cor. found.

Gregory K. Miller, LS #2004 - For: Champion International Corp. - June/Oct. 1984 - M 97-68 and C.S. File 58/146

Found - 58" Fir stump with bark scribed "BT" visible. I accept this as the orig. 1879 Fir BT.

The orig. Maple is missing.

Set - At record bearing & dist. from the Fir BT (stump) I set: A 2½" brass cap attached to a 2½" x 30" galv. IP with flared bottom and mkd: T23S R10W ¼ S26 S25 1984 RPLS 2004.

Accessories -

58" Fir stump bears due West 46.2 ft. (1879 BT)

37" Cedar stump bears N.67°E., 11.7 ft. (not of rec.) scribed T22S S26W)

New BTs- 16" Fir bears N.12°E., 19.3 ft. (1984 BT) ¼ S25 BT.

18" Fir bears N.82°W., 24.0 ft. scribed ¼ S26 BT.

Note - Due to the upcoming logging operations, I have removed and have in my possession the piece of bark with the scribed "BT" visible. I will replace it after operations are completed.

Fd. Ok by T. Hostetter, 8/1996 M 126-31