

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 654700

PRIMARY CORNER DESCRIPTION SE Cor. Sec. 36, T22-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 279 survey dated March 5, 1878 (DCSO records Vol. 4 Page(s) 1648)

Set a stone for corner to T22 and 23 S., R. 9 and 10 W., stone 6 x 14 x 16. Made stone mound 4 x 2 ft. No timber convenient for witness.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - Oct. 26, 1967 - C.S. File 55/68

Found - Original stone 6x14x16" in 4 ft. x 2 ft. mound of stone, found in place, from which a:
Ridge top, NW and SE, bears North 300 lks., now in place.
Ridge top, NW and SE, bears East 300 lks., now in place.

Set 1½" x 36" galv. iron pipe with 3" brass cap marked: "Oreg. St. Bd. of Forestry T22S R10W R9W S36 S31 S1 T23S R10W 1967 RS359", 30" in ground, alongside corner stone in mound of rock and from which:

17" Fir bears N.73½°E., 20.9 ft. to face, scribed T22S R9W S31 BT RS 359.

27" Fir bears N.21°W., 24.5 ft. to face; scribed T22S R10W S36 BT.

Set 4" x 4" x 72" white painted cedar post 1.6 ft. W. of corner pipe. Oregon State Forestry Dept. metal location poster on 27" Fir BT.

Fd. and used in BLM survey by Jelley and Steward, under Group #703, surveyed July 1969/May 1970 - (DCSO records, Vol. 35 Page 14549)

Fd. OK, April 1987 by D. Baker, C.S. File 63/50 and M 104-19