

TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 700640

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 1 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 6 Page(s) 2632)

Set an Alder post 36 x 5, 18" in ground for ¼ sec. corner between secs. 1 and 12, from which
An Alder 8" dia., bears S.15°E., 39 lks. dist.
A Fir 40" dia., bears N.60°W., 149 lks. dist.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #688 dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2697)

Fire has destroyed ¼ sec. cor. and bearing trees.

BLM resurvey by James E. Jelley and Rolla R. Steward, Cadastral Surveyors under Group # 703, surveyed July 1969/May 1970 (DCSO records Vol. 35 Page(s) 14550-51)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., level with the surface of ground, with brass cap mkd: ¼ S 1
T 23 S
R 10 W
1970

from which
A sawed Fir stump 25" dia., bears S.0½°W., 70 lks. dist. mkd. ¼ S1 BT.
An Alder 18" dia., bears S.30½°W., 30 lks. dist. mkd. X BT
Raise a mound of stone, 2 ft. base, 2 ft. high, to the W. and deposit broken green glass at base of iron post.