

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5 only, (North)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 18 Page(s) 7488-89)

-----  
(At a point, 2.24 chs. West of ¼ sec. cor. of 32) Set a basalt stone 18x11x8 ins., 12" in the ground for cor. to secs. 4 and 5, mkd. with 4 notches on E. and 2 notches on W. edges, from which

A Fir 10" dia., bears N.40°W., 7 lks. dist. mkd. T31S R1W S33 BT.

A Fir 8" dia., bears S.65°E., 8 lks. dist. mkd. T32S R1W S4 BT.

A Matherone 8" dia., bears S.18°W., 28 lks. dist. mkd. T32S R1W S5 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - Aug. 1, 1968 - C.S. File 54/71

-----  
Found - Stone at corner, 18x11x8 with 4 grooves on it.  
10" Fir now a stob, N.40°W., 4.6 ft., opened and found scribing of "BT"

8" Fir now pieces of wood and a hole, S.65°E., 5.3 ft.

8" Laurel now a stump hole, S.18°W., 18.5 ft.

Set Brass cap at cor. mkd: County Surveyors Office

T31S R1W S 33  
T32S 1968 S 5 | S 4

New BTs- 15" D.Fir S.21°E., 26.3 ft. mkd. T32S R1W S4 CS BT

10" Y.Pine S.65°W., 25.1 ft. mkd. T32S R1W S5 CS BT

Cor. lies N-W fence, 150.1 ft. W. of ¼ cor. sec. 33 only and 300 ft. North of a road.

Fd. OK, Dec. 1992 by Kaiser - M 116-30

Neil Hibbs - For: Gilliam Family Living Trust - 6/2015 - 2015-0017A-B

-----  
Condition report only

Found - Brass cap

28" Fir BT w/healed face bears S.21°E., 23.9'

24" Pine BT w/healed face bears S.65°W., 25.1'

Stone alongside monument.