

RECOVERED MONUMENT LIST

PT. NO.	LDP NORTHING	LDP EASTING	STATION	OFFSET	DATE	DESCRIPTION & REFERENCE DOCUMENTS
1036	604264.636	4162585.629	"CR"12+25.25	-35.13	5-8-03	FND. 3/4" I. REBAR 3 1/2" ABOVE SURFACE, GOOD CONDITION, WOOD POST NEARBY
1037	604193.545	4162562.989	"CR"11+99.03	34.75	5-8-03	FND. 5/8" I. ROD W/1 1/4" PLASTIC CAP STAMPED "BENTZ SURVEY INC.", 1 1/2" ABOVE SURFACE, GOOD CONDITION (REF. #M90-64)
1038	606039.033	4162919.863	N/A	N/A	5-13-03	FND. 1 1/4" PLASTIC CAP STAMPED "BTS ENG-SURV", 1/2" BELOW SURFACE, GOOD CONDITION (REF. #2003-0063)
1039	606010.740	4162743.265	2255+55.03	-149.86	5-13-03	FND. 1 1/4" PLASTIC CAP STAMPED "AA SURVEYING", 1" ABOVE SURFACE, GOOD CONDITION (REF. #M119-8)
1040	606241.260	4162847.232	2253+03.78	-149.46	5-13-03	FND. 1 1/4" PLASTIC CAP STAMPED "AA SURVEYING", 1 1/2" ABOVE SURFACE, GOOD CONDITION (REF. #M119-8)
1041	606523.593	4162967.905	2250+00.68	-149.20	5-13-03	FND. 1 1/4" PLASTIC CAP STAMPED "AA SURVEYING", 2 1/2" ABOVE SURFACE, GOOD CONDITION (REF. #M119-8)
1042	607526.669	4163319.582	N/A	N/A	5-13-03	FND. 1 1/4" PLASTIC CAP STAMPED "BTS ENG-SURV", 1" ABOVE SURFACE, GOOD CONDITION (REF. #2003-0063)
1043	605214.607	4162615.610	"OS"2246+11.54	48.24	5-12-03	FND. 5/8" I. ROD 2" BELOW A.C., GOOD CONDITION (REF. #M119-8)
1044	604726.649	4162156.022	2269+67.03	-149.78	5-13-03	FND. 5/8" I. ROD FLUSH W/SURFACE, GOOD CONDITION (REF. #M119-8)
1045	602680.593	4161808.327	N/A	N/A	5-8-03	FND. 3/4" I. ROD FLUSH W/CONC. STEPS, GOOD CONDITION (REF. #M39-70)
1046	602691.964	4161810.078	N/A	N/A	5-8-03	FND. 1 1/4" PLASTIC CAP ON 5/8" I. REBAR STAMPED "LANDMARK", 4 1/2" ABOVE SURFACE, UNSTEADY POSITION (REF. #M139-49)
1047	602766.721	4161883.136	N/A	N/A	5-8-03	FND. 1 1/4" PLASTIC CAP STAMPED "LANDMARK" ON 5/8" I. REBAR, 6" ABOVE SURFACE, GOOD CONDITION (REF. #M139-49)
1048	602695.600	4161792.012	N/A	N/A	5-8-03	FND. 1 1/4" PLASTIC CAP STAMPED "LANDMARK", FLUSH W/SURFACE, GOOD CONDITION (REF. #M139-49)
1049	602683.545	4161730.659	N/A	N/A	5-8-03	FND. 5/8" I. REBAR W/1 1/4" PLASTIC CAP STAMPED "LANDMARK", 2" ABOVE SURFACE, GOOD CONDITION (REF. #M139-49)
1050	602713.929	4161716.517	N/A	N/A	5-8-03	FND. 1 1/4" PLASTIC CAP STAMPED "LANDMARK" FLUSH W/SURFACE, GOOD CONDITION (REF. #M139-49)
1051	604245.902	4163321.017	"CR"19+56.62	43.88	5-8-03	FND. 5/8" I. REBAR W/1 1/4" PLASTIC CAP, 8" ABOVE SURFACE, FAIR CONDITION
1052	604329.551	4163314.760	"CR"19+57.25	-40.00	5-8-03	FND. 5/8" I. REBAR 4" ABOVE SURFACE, GOOD CONDITION, WOOD POST ON GROUND NEARBY
1053	603473.898	4161060.339	"DR"6+99.88	30.17	5-8-03	FND. 5/8" I. REBAR 3" BELOW SURFACE, GOOD CONDITION
1054	603415.531	4161044.996	"DR"7+00.11	-30.17	5-8-03	FND. 5/8" I. REBAR 7" BELOW SURFACE, GOOD CONDITION
1055	603746.930	4159678.213	"DR"20+99.05	-60.00	5-8-03	FND. 5/8" I. ROD 1" BELOW SURFACE, GOOD CONDITION
1056	600822.456	4162111.270	"P"2+19.37	34.27	5-7-03	FND. 1 1/4" PLASTIC CAP STAMPED "I.E. ENG", 1" BELOW SURFACE, GOOD CONDITION (REF. #RM2-45)
1057	600807.946	4162088.754	"P"1+92.59	34.72	5-7-03	FND. 5/8" I. ROD 7" BELOW SURFACE, BENT TO SOUTH, TIED WHERE ROD ENTERS GROUND, POOR CONDITION (REF. #RM3-25)
1058	600921.401	4162262.453	"P"4+00.00	30.00	5-7-03	FND. 5/8" I. ROD, 1" BELOW SURFACE, GOOD CONDITION
1059	601029.371	4162313.079	"P"4+99.98	-35.00	5-7-03	FND. 5/8" I. ROD FLUSH W/SURFACE, GOOD CONDITION
1060	601295.052	4161821.559	"PW"1+00.00	-30.00	5-7-03	FND. 5/8" I. REBAR 4" BELOW SURFACE, GOOD CONDITION
1061	601605.809	4162157.863	"PW"5+53.95	30.00	5-8-03	FND. 1/2" I. ROD 7" ABOVE SURFACE, GOOD CONDITION (REF. #M44-77)
1062	601535.408	4162099.444	"PW"4+62.47	30.07	5-12-03	FND. 5/8" I. ROD W/1 1/4" PLASTIC CAP STAMPED "I.E. ENGINEERING", 1 1/2" ABOVE SURFACE, GOOD CONDITION (REF. #1998-0065)
1063	604482.955	4161450.314	"C1"2275+94.05	60.06	5-12-03	FND. 5/8" I. ROD 11" BELOW SURFACE, GOOD CONDITION (ODOT R/W DRG. NO. 7B-7-10)
1064	604540.084	4161544.614	"C1"2274+93.97	60.00	6-30-03	FND. 1/2" I. ROD 1.7 FT. BELOW SURFACE, GOOD CONDITION (ODOT R/W DRG. NO. 7B-7-10)
1065	604073.202	4161286.107	"C1"2280+04.08	60.00	5-8-03	FND. 5/8" I. ROD 6" BELOW SURFACE, BENT TO SOUTH, TIED WHERE ROD ENTERS GROUND, POOR CONDITION (ODOT R/W DRG. NO. 7B-7-10)
1066	604244.714	4163280.843	"CR"19+16.48	41.77	5-8-03	FND. 5/8" I. ROD W/1 1/4" PLASTIC CAP, 9" ABOVE SURFACE, FAIR CONDITION
1067	606182.675	4164011.990	N/A	N/A	5-13-03	FND. 2 1/2" BRASS CAP STAMPED "COUNTY SURVEYORS OFFICE T26S R6/5W 1/4 S24 S19 1964", 4" BELOW SURFACE, GOOD CONDITION, METAL FENCE POST NEARBY
1068	601478.642	4159718.974	N/A	N/A	5-13-03	FND. 2" I.D. I. PIPE 14" BELOW SURFACE, GOOD CONDITION, BELIEVED TO BE THE SW COR. D.L.C. 44
1070	603893.798	4162251.003	N/A	N/A	5-8-03	FND. 5/8" I. REBAR 14 1/2" ABOVE SURFACE, GOOD CONDITION
1100	601017.721	4161294.318	N/A	N/A	12-18-03	FND. 3/4" I. ROD FLUSH W/SURFACE, GOOD CONDITION (REF. #M20-72)
1101	600875.151	4161288.710	N/A	N/A	12-18-03	FND. 1/2" INSIDE DIA. PIPE 0.6' ABOVE SURFACE, BENT TOWARDS THE N.E. (REF. #M24-29)
1102	600887.839	4161008.835	N/A	N/A	12-18-03	FND. 1/2" INSIDE DIA. PIPE FLUSH W/SURFACE, GOOD CONDITION (REF. #M24-29)
1103	600952.416	4160991.303	N/A	N/A	12-18-03	FND. 3/4" I. ROD 0.5' BELOW SURFACE, LEANS SOUTHWESTERLY, TIED WHERE ENTERS GROUND (REF. #M20-72)
1104	600644.531	4162201.449	N/A	N/A	12-18-03	FND. 5/8" REBAR FLUSH W/SURFACE, GOOD CONDITION (REF. #RM 3-25)
1105	600772.033	4162386.488	N/A	N/A	12-18-03	FND. 2" INSIDE DIA. PIPE, 4" ABOVE SURFACE, GOOD CONDITION (REF. VOL. 6, P.31)
N02	602996.345	4161677.740	N/A	N/A	5-8-03	FND. 3 5/8" BRASS DISK SET IN CONC. STAMPED "US COAST & GEODETIC SURVEY REFERENCE MARK, FOR INFORMATION WRITE TO THE DIRECTOR WASHINGTON D.C., WINCHESTER N02 1953"
1106	599039.612	4161725.206	2328+10.02	-99.94	1-28-04	FND. 5/8" I. ROD SET IN CONC. 0.1 FT. ABOVE SURFACE, FAIR CONDITION, 4X4 WOOD POST NEARBY UNREADABLE.

FILED  
 Date: 4-15-2004 By: JC  
 This survey consists of:  
 Map: ST HWY 15-016 A-K  
 Name: \_\_\_\_\_  
 Corner Ppt: \_\_\_\_\_  
 DOUGLAS COUNTY  
 SURVEYOR

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR  
*Christine V. Blewins*  
 OREGON  
 JULY 19, 1994  
 CHRISTINE V. BLEWINS  
 2009  
 EXPIRES: DEC. 31, 2005

OREGON DEPARTMENT OF TRANSPORTATION  
 HORIZONTAL CONTROL, RECOVERY AND RETRACEMENT MAP  
 I-5: EXIT 129 / N. UMPQUA RIVER (WINCHESTER) BRIDGES  
 INTERSTATE 5 AND OAKLAND-SHADY HIGHWAY  
 DOUGLAS COUNTY  
 MARCH 24, 2004 FOR ODOT REGION 3  
 3500 NW STEWART PARKWAY ROSEBURG, OR 97470  
 SHEET 5 OF 11